

FRACTIONAL O-RING GAUGE COMMON SIZES DISPLAYED

- 1. Use thickness gauge to determine proper width.
- 2. Lay O-Ring on paper to determine both inside & outside diameter



1/8


3/32

3/16

1/16

If you need assistance with measurements please contacts your Patlin Representative.

Please use this gauge as a reference, accuracy may vary based upon printer settings. Patlin Inc. assumes no responsibility for the accuracy of measurement while using this gauge.






In






METRIC O-RING GAUGE

- 1. Use thickness gauge to determine proper width.
- 2. Lay O-Ring on paper to determine both inside & outside diameter



If you need assistance with measurements please contacts your Patlin Representative.



Please use this gauge as a reference, accuracy may vary based upon printer settings. Patlin Inc. assumes no responsibility for the accuracy of measurement while using this gauge.



